



## TABELA UPOGIBNEGA ORODJA za JUTEC

D = dimenzija cevi ( v mm )

R = upogibni polmer do srednjice ( v mm )

D	R
10	25
	36
	30
	45
	89
12	36
	50
14	30
	36
	42
15	35
	40
16	40
	48
	55
	60
17	40
18	45
	55
	65
	69
	88
	105
19	40

D	R
20	40
	50
	53
	60
	82
21	40
	50
	67
22	45
	50
	60
	82
	105
24	110
	45
	50
25	76
	40
	46
	65
	80
	110
26	247,5
	65
	80
27	114
	80

D	R
28	60
	80
	90
	112
30	75
	82
	90
	110
33	85
	125
35	110
36	110
37	150
40	170
48	213
60	200



## TABELA UPOGIBNEGA ORODJA za PULZER CNC

D = dimenzija cevi ( v mm )    R = upogibni polmer do srednjice ( v mm )

D	R	D	R	D	R	D	R
13,5	50	30	60	40	90	60	120
14	65		75		109		160
	80		75-kr.		145		250
15	50	30	80	42	65	63	189
	80		100		90	70	210
16	50		140		90-kr.	73	174
	20	50	32		60	100	76
70		85			117	250	
21	50	33	60		130	370	
	75		70	145	410		
	200		80	155			
22	60		100	190			
	125		117	240			
25	50		35	125	45	125	
	60	65		48		70	
	65	100				90	
	75	117				90-kr.	
	77	38	65	50	120		
	105		75		90		
	134		95		95		
26	50	125	51		125		
	55	130		300			
	65	38	145	57	90		
	75		167		140		
	108				174		
28	60				300		